



Product Information

Date: *March 4 2013*

Product: PCS200 (GSM/GPRS Communicator Module)

Subject: New firmware version 2.52 released

Downloads: To download firmware v2.52, *[click here](#)
To download the firmware upgrade instructions, [click here](#)
**requires login name and password to download*

Resolved Issues: **Arming/Disarming confirmation SMS on multiple partitions sending incorrect information**

When using Arming/Disarming SMS with a multi-partitioned MG/SP panel, the SMS that is sent by the PCS200 could indicate the incorrect status when only one of the partitions is armed by SMS, such as indicating a partition is disarmed when it is actually armed.

IP address was not acquired from the provider

In certain instances, all the APN programming information was correct as per the mobile provider, however the network was not assigning an IP address to the module; we have modified the algorithm used during this process to protect against this situation.

Incorrect port number in the callback SMS

If you use a higher port number (example 47998) for your WinLoad callback connection, if the connection is not properly completed, the SMS that was returned did not indicate the proper port number.

Improvements **Synchronization with the IP/GPRS receiver**

The synchronization between the PCS200 and the IP/GPRS receiver was improved to protect against data loss on certain networks.

Contact: If you require additional information or if you have any questions, please do not hesitate to contact our support department.

Email: distributorsupport@paradox.com

Fax: +1.450.491.2313

Phone: 1.800.791.1919 (N. America)
+1.450.491.7444 (International)

Paradox Security Systems LTD - Product Information #PCS200-013-03-04