



Product Information

Date: *January 10th, 2013*

Product: IP150 Internet Module

Subject: New release version 1.23

Downloads: To download the firmware V1.23, [click here](#)
For the firmware upgrade instructions, [click here](#)
*requires login name and password to download

Resolved Email for PCS disconnect

Issue: If the connection is lost from the panel to the PCS250, the IP150 now sends an email to signal this disconnection.

HTTPS activation

HTTP will now deactivate when HTTPS is activated, in previous version, the HTTP would still be available if HTTPS was activated.

Remove module button

The Remove Module button will appear on all languages now. The Remove Module button will appear when you disconnect the PCS250 from the IP150's serial port, but in all languages except for English, it did not appear.

Module removed email

The module will now properly send the email for the Module Removed event, this event will be generated when a module is disconnected and a [4005] module scan is performed, in the previous version, the event that was being sent was "Wireless zone low battery restored".

Improvements: iParadox communication on a 3G network

A validation process has been added to ensure proper communication between the iParadox and the IP150 on a crowded 3G cellular network. In previous version, users were experiencing "Timeout" errors being displayed when trying to connect with the App in rare cases

Contact: If you require any additional information or if you have any questions, please do not hesitate to contact our Support department.

Email: support@paradox.com

Phone: +1.450.491.7444 (International)

Paradox Security Systems LTD – Product Information #IP150-013-01-10