



## Product Information

**Date:** *November 17th, 2015*

**Product:** NVX80 Indoor/Outdoor Motion Detector

**Subject:** New NVX80 firmware version 1.16 release.

**Downloads:** To download the NVX80 firmware v1.16, \*[click here](#)

To download the NVX80 reference and installation manual which includes firmware upgrade instructions, \*[click here](#)

*\*requires user login and password to download*

**Resolved Issues: OLED Down Button non Responsive**

In a small percentage of units with firmware version 1.15, the down arrow button below the OLED screen may sometimes become unresponsive. You would then have to use the up arrow button to scroll through the OLED programming menu. Firmware version 1.16 corrects this situation.

**Contact:** If you require any additional information or if you have any questions, please do not hesitate to contact our Distributor Support department.

Email: [distributorsupport@paradox.com](mailto:distributorsupport@paradox.com)

Phone: +1.450.491.7444 (International)

Paradox Security Systems LTD – Product Information # NVX80-15-11-17